
PORT & COMPANY

HOW TO MEASURE



CHEST

With arms down at sides, measure around the upper body, under arms and over the fullest part of the chest.

SIZE CHART

	S	М	L	XL	2XL	3XL	4XL	
Chest	35-37	38-40	41-43	44-46	47-49	50-53	54-57	

COLOR INFORMATION




Ro yal

PMS 2133 C

Red

PMS 200 C



Deep Navy

Gold

PMS 137 C

Dark Green



6 C

Port & Company[®] Performance Tee. PC380

Our value-priced polyester tee performs with Dry Zone[®] moisture-wicking technology to keep you cool, dry and comfortable.

- 3.8-ounce, 100% polyester
- Tag-free label

Due to the nature of 100% polyester performance fabrics, special care must be taken throughout the screen printing process.

Given the extreme heat required for sublimation, please consult with your decorator. It is highly recommended to sample test product by color before production.

CARE INSTRUCTIONS Machine wash cold, inside out with like colors, only

non-chlorine bleach when needed. Tumble dry low. Do not iron. Do not use fabric softener.







S	Μ	L	XL	2XL	3XL	4XL
35-37	38-40	41-43	44-46	47-49	50-53	54-57



Jet Black Neon Blue PMS BLACK 6 C PMS 801 C

Neon Green PMS 909 C

Neon Orange Neon Pink PMS 811 C PMS 926 C

